





ORDER CODE HN002055 HT2055 METER FOR STEP/CONTACT VOLTAGE UP TO 50A

HT2055 consists in a **power unit** and a **voltmetric unit**, necessary for carrying out step and contact voltage measurements in **industrial installations** (such as TN systems, transformer cabinets) with a rated test current up to 50A. The two units, synchronized in time and current are capable of providing the correct value of step and contact voltages consistently with the real current values measured by the power unit, also taking into consideration the disturbance effects found on the measured circuit. It is also capable of measuring earth resistance and ground resistivity by the classical voltammetric method.

These measurements can be saved in the **internal memory** of the voltmetric unit and downloaded onto the PC through the provided Windows software.







Soft carrying bag for remote unit and accessories

Cable 10mm² with cable winder and alligator clip, 50m

Measurement of step/contact voltage with separate units

- Synchronization of units for correct measurements
- · Test current selectable up to 50A
- LCD display on both units

Characteristics

Power unit

- Power supply: 110/230V AC, 50/60Hz
- Output power: 900VA
- Output current: max 55A
- Test frequency: 55Hz
- Voltage measurement: 0.1÷999V
- Resolution: 0.1÷1V
- Basic accuracy: ±2%reading
- Display: LCD 240x128 dots + backlight
- Memory: 2000 locations
- Communication interface: RS-232
- Measurement category: CAT III 300V
- Protection: fuse T 6.3A/250V
- Pollution level: 2
- Mechanical protection: IP40 (closed case)
- Size (LxWxH): 335x335x160mm
- Weight: 28kg

Voltmetric unit

- Voltage measurement: 0.1÷999V
- Resolution: 0.1÷1V
- Resistance measurement: 0.001÷99.99Ω
- Resolution: 0.01Ω
- Basic accuracy: ±2%reading
- Input impedance: Selectable $1k\Omega/1M\Omega$
- Display: LCD 240x128 dots + backlight
- Memory: 2000 locations
- Communication interface: RS-232/USB
- Power supply: 6x1.2V rechargeable batteries type AA
- Pollution level: 2
- Mechanical protection: IP40
- Size (LxWxH): 230x115x103mm
- Weight: 1.3kg



	Power supply cable of power unit
	Metal plate (200x100mm), 2 pieces
	Current metal probe
	Voltage metal probe
	Cable 10mm ² with winder and alligator clip, 50m
	Cable 10mm ² with alligator clip, 10m
	Black measuring cable, 3m, with industrial plugs, 2 pcs.
	Green measuring cable, 10m
	Black measuring cable, 1.5m
	Red measuring cable, 50m
	Red connection cable with alligator clip, 1m
5004-IECN	Alligator clip, 4 pieces
	Cable RS-232
C2007	USB cable
	Soft transport bag, 2 pieces
	Strap for slinging the device over one's shoulder
	6 x 1.2V rechargeable batteries NiMH type AA
	External power supply
TERAVIEW	Windows software on CD-ROM
	User manual and ISO9000 calibration certificate



Red measuring cable, 50m



Black measuring cable, 3m, with industrial plugs, 2 pieces

- · Earth resistance measurement
- · Compensation function of disturbance effects
- · Internal memory for measured data saving
- · USB and RS-232 ports for communication between unit and PC

Optional accessories

Metal probe, 1m long Metal probe, 60cm long

For further information on optional accessories, please contact HT.